

H-K Building # 40  
 Project Number: 0980193E  
 Project: G. HEILEMAN BREWERY "E"  
 Date Inspected: 03/27/89  
 Inspector: TIM SWARTZ

ASBESTOS ASSESSMENT SURVEY

Building Number: 40  
 Building Name: WAREHOUSE  
 SEATTLE, WASHINGTON  
 Building Type: WAREHOUSE  
 Year Constructed: 1979

*****	AREA NUMBER: 01	AREA DESCRIPTION: 1st Floor-Pasteurizer	AREA AVERAGE % ASBESTOS: 0%	*****
-------	-----------------	---	-----------------------------	-------

LOCATION OF THE MATERIAL	SAMPLE NUMBER	ASB	MATERIAL DESCRIPTION	O&M CODE	QUANTITY	UNITS OF MEASURE	PIPE ID	EXP POT	PL	REMOVAL COSTS	REPLACEMENT COSTS	TOTAL COSTS
south side of bottle machine-on wall	00-356176	0%	pipe covering	OMA	60 ft.	4 in. O.D.	HPS/R					
south side of bottle machine-on wall	00-356176	0%	pipe covering	OMA	55 ft.	6 in. O.D.	HPS/R					
west side of bottle machine	00-356176	0%	pipe covering	OMA	25 ft.	4 in. O.D.	HPS/R					
north side of bottle machine	00-356176	0%	pipe covering	OMA	25 ft.	4 in. O.D.	HPS/R					
south side-attached to bottle machine	00-356300	0%	pipe covering	OMA	85 ft.	4 in. O.D.	HPS/R					
south side-attached to bottle machine	00-356300	0%	pipe covering	OMA	25 ft.	6 in. O.D.	HPS/R					
south side-attached to bottle machine	01-356292	0%	mjp on pipe covering	OMA	6	4 in. O.D.	HPS/R					
south side-attached to bottle machine	01-356292	0%	mjp on pipe covering	OMA	12	6 in. O.D.	HPS/R					
	01-356293	0%										
	01-356294	0%										

AREA COMMENTS

AREA # 01	TOTAL	\$0	\$0	\$0
-----------	-------	-----	-----	-----

BUILDING # 40	TOTAL	\$0	\$0	\$0
---------------	-------	-----	-----	-----